

Fig. 1.




Fig. 2A.




Fig. 2B.




Fig. 2C.




Fig. 2D.





Fig. 2E.








Fig. 3.

3/10





SHEET RESISTANCE CHANGE WITH ANNEALING TEMPERATURE
FOR THE DEPOSITS WITH AND WITHOUT $(\text{NH}_4)_2\text{SO}_4$





Fig. 4C.

6/10



7/10




Fig.5.

8/10




Fig.6A.

9/10




Fig.6B.




Fig. 7.